RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed 2023

PVC roof restoration

Mineral Wells, Texas



Completed industrial roof restoration

290,000 sq. ft.	20-year L&M warranty	Aged PVC / metal details

THE CHALLENGE

Recurring leaks affected an aged PVC roof at an occupied industrial facility. Replacement would have added cost, waste and disruption to daily operations.

THE RAMTECH APPROACH

Evaluate the roof, repair and reinforce leak points, prepare the PVC membrane and metal transitions, then apply high-solids silicone restoration.

THE RESULT

The completed system provides restored watertight integrity, a reflective finish and 20-year manufacturer labor-and-material protection without full tear-off.

RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed 2019

Modified-bitumen restoration

Jackson, Mississippi



Roof photograph

76,647 sq. ft.	20-year L&M warranty	Occupied medical facility

THE CHALLENGE

Aged modified-bitumen roofs showed granule loss and leaks in a busy city-center medical environment. The facility needed waterproofing while remaining accessible.

THE RAMTECH APPROACH

Evaluate the roof, review moisture conditions, repair leak points and vulnerable details, prepare the surface and apply high-solids silicone restoration.

THE RESULT

The completed system provides restored watertight integrity, a reflective finish and 20-year warranted protection with minimal disruption.


RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed 2014

R-panel metal restoration

Round Rock, Texas



Restored R-panel metal roof

61,334 sq. ft.	10-year L&M warranty	Office / warehouse center

THE CHALLENGE

Leaks affected an office and warehouse center operating six days per week. Service vehicles continued to move through the property, making shutdown impractical.

THE RAMTECH APPROACH

Evaluate the roof, repair active leaks and metal details, clean and prepare R-panel surfaces, verify coverage and apply high-solids silicone restoration.

THE RESULT

The completed system provides restored watertight integrity, a reflective finish and 10-year warranted protection without business shutdown.

Repair first. Restore second. Replace last.

800-883-9018 | ramtechroofing.com

COMMERCIAL & INDUSTRIAL ROOF RESTORATION

RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed project

Metal roof restoration

Malakoff, Texas



Manufacturing-facility roof

80,000+ sq. ft.	20-year warranty	Standing-seam metal

THE CHALLENGE

Oxidation, fastener movement and leaks at seams and penetrations affected an aging manufacturing-facility roof. Replacement would have caused expense and operational disruption.

THE RAMTECH APPROACH

Evaluate the roof, reinforce fasteners, restore seams and penetrations, prepare surfaces and apply a fluid-applied restoration system with quality checks throughout installation.

THE RESULT

The completed system restored waterproof integrity, eliminated leaks, improved reflectivity and extended roof service life while avoiding tear-off. The completed project carries a 20-year warranty.

Repair first. Restore second. Replace last.

800-883-9018 | ramtechroofing.com

COMMERCIAL & INDUSTRIAL ROOF RESTORATION

RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed 2025

Multi-system roof restoration

Athens, Texas



Manufacturing facility

320,000+ sq. ft.	20-year L&M warranty	Metal / TPO / modified bitumen

THE CHALLENGE

Multiple roof systems experienced aging, leaks and ponding water. The occupied manufacturing facility needed a durable solution with limited interruption to daily operations.

THE RAMTECH APPROACH

Investigate moisture conditions, complete core sampling and adhesion testing, reinforce seams and penetrations, and install a high-performance reflective restoration system.

THE RESULT

The completed project provides a restored roof without tear-off, a reflective finish and a 20-year manufacturer labor-and-material warranty.

Repair first. Restore second. Replace last.

800-883-9018 | ramtechroofing.com

COMMERCIAL & INDUSTRIAL ROOF RESTORATION

RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed project

Manufacturing roof restoration

Manufacturing facility | North Texas



Completed roof restoration

Modified bitumen	20-year manufacturer-backed	Facility restoration

THE CHALLENGE

The existing roof included equipment, pipes and penetrations requiring careful preparation before the restoration coating.

THE RAMTECH APPROACH

Prepare the surface and treat details around rooftop equipment and penetrations. The project film follows the work through coating application.

THE RESULT

Closing aerial footage documents the completed white roof surface. The completed project includes a watertight result and a 20-year manufacturer-backed warranty.

Repair first. Restore second. Replace last.

800-883-9018 | ramtechroofing.com

COMMERCIAL & INDUSTRIAL ROOF RESTORATION

RAMTECH ROOFING
REPAIRS • RESTORATIONS • COMMERCIAL ROOFING

PROJECT PROFILE

Completed project

Gymnasium roof restoration

School gymnasium | Texas Hill Country



Completed roof restoration

Modified bitumen	20-year L&M warranty	School roof restoration

THE CHALLENGE

The gymnasium had an aged modified-bitumen roof with seams and penetrations requiring preparation and detail work.

THE RAMTECH APPROACH

Power-wash the roof, treat seams and penetrations, and apply the restoration coating. On-roof and aerial footage document the work stages.

THE RESULT

Closing footage shows the restored white roof surface. The completed project includes a 20-year labor-and-material warranty.